



**Product information** 



Measuring and Calibration Box

- OFFSET Correction value for soldering tip temperature

- SETBACK Reduction of the set temperature after a specified period of time

- LOCK Locking the set temperature

- °C/°F Switching temperature diplay °C/°F

- WINDOW Setting a set value window. If the actual temperature is within the set value window a potential-free contact is activated

- Temperature measuring tips are available for each soldering iron

WCB2 Measuring and Calibration Box

- OFFSET: Correction value for soldering tip temperature
- SETBACK: Reduction of the set temperature after a specified period of time
- LOCK: Locking the set temperature
- °C/°F: Switching temperature diplay °C/°F

- WINDOW: Setting a set value window. If the actual temperature is within the set value window a potential-free contact is activated

- Temperature measuring tips are available for each soldering iron